

Inspection Photos
Location Name: Iles Dome Unit 38
API: 05-081-07660



Photo 1. Overview of location taken at entrance facing north.

Inspection Photos
Location Name: Iles Dome Unit 38
API: 05-081-07660



Photo 2. Equipment stored on location.



Photo 3. Equipment stored on location. No secondary containment.