

Inspection Photos
Location Name: Hebron/Marr 7
Location ID: 413754



Photo 1. Overview of location taken at entrance facing northwest.

Inspection Photos
Location Name: Hebron/Marr 7
Location ID: 413754



Photo 2. Cellar full of fluid.



Photo 3. Close up of fluid in cellar.

Inspection Photos
Location Name: Hebron/Marr 7
Location ID: 413754



Photo 4. Trench that appears to funnel stormwater into cellars.



Photo 5. Stained soil near wellhead.

Inspection Photos
Location Name: Hebron/Marr 7
Location ID: 413754



Photo 6. Stained soil near wellhead.



Photo 7. Stained soil at wellhead.