

**Inspection Photo**  
**Beaver creek ranch 08-14B**  
**API # 045-18823**  
**Inspection # 689301979**



**Location Photo #1**



**Location Photo #2**

**Inspection Photo**  
**Beaver creek ranch 08-14B**  
**API # 045-18823**  
**Inspection # 689301979**



**Location Photo #3, oily residue on side of tanks.**



**Location Photo #4, oily residue on sde of tanks.**



**Inspection Photo**  
**Beaver creek ranch 08-14B**  
**API # 045-18823**  
**Inspection # 689301979**



**Location Photo #5, stained rock in battery containment.**



**Location Photo #6, stained rock in battery containment.**

**Inspection Photo**  
**Beaver creek ranch 08-14B**  
**API # 045-18823**  
**Inspection # 689301979**



**Location Photo #7, stained rock in battery containment.**