

**Inspection Photo**  
**Youberg 444-7**  
**API # 045-22511**  
**Inspection # 689301981**



**Location Photo #1**

**Location Photo #2**

**Inspection Photo  
Youberg 444-7  
API # 045-22511  
Inspection # 689301981**



**Location Photo #3, unused equipment.**



**Location Photo #4, unused equipment.**

**Inspection Photo  
Youberg 444-7  
API # 045-22511  
Inspection # 689301981**



**Location Photo #5, unused equipment North edge of location**



**Location Photo #6, stained ground all over location.**

**Inspection Photo**  
**Youberg 444-7**  
**API # 045-22511**  
**Inspection # 689301981**



**Location Photo #7, Stained ground**



**Location Photo #8, Debris, frac sand.**

**Inspection Photo**  
**Youberg 444-7**  
**API # 045-22511**  
**Inspection # 689301981**



**Location Photo #9, Debris, frac sand on the south end of separators.**



**Location Photo #10, Debris, frac sand, near flow line by tank.**

**Inspection Photo  
Youberg 444-7  
API # 045-22511  
Inspection # 689301981**



**Location Photo #11, Debris, frac sand behind separators.**



**Location Photo #12, Debris, frac sand near front of the separators.**

**Inspection Photo  
Youberg 444-7  
API # 045-22511  
Inspection # 689301981**



**Location Photo #13, Unused equipment on lease access road.**



**Location Photo #14, Unused equipment on lease access road.**

