

Inspection Photo
Federal RU 312-17
API # 045-23736
Inspection # 689301982



Location Photo #1



Location Photo #2

**Inspection Photo
Federal RU 312-17
API # 045-23736
Inspection # 689301982**



Location Photo #3, Stained ground south end of separators.



Location Photo #4, Stained ground North end of separators.

Inspection Photo
Federal RU 312-17
API # 045-23736
Inspection # 689301982



Location Photo #5, Stained ground near solar panels



Location Photo #6, Stained ground around wellheads.

Inspection Photo
Federal RU 312-17
API # 045-23736
Inspection # 689301982



Location Photo #7, Stained soil at wellheads.



Location Photo #8, Stained soil near wellheads.

Inspection Photo
Federal RU 312-17
API # 045-23736
Inspection # 689301982



Location Photo #9, Stained soil near wellheads.

