

## Inspection Photos

Location Name: Kern- 612N62W / 33NESE

Location #: 318918



**Photo #1**

**Kern 43-33 (API # 05-123-10268) wellsite**

**P&A'd**



**Photo #2**

**Kern 43-33 P&A'd wellsite**

**Unused equipment on site - Tubing**



## Inspection Photos

Location Name: Kern- 612N62W / 33NESE

Location #: 318918



**Photo #3**

**Kern 43-33** Adandoned battery site

**Facing West**



**Photo #4**

**Kern 43-33** Adandoned battery site

**Facing East**



**Inspection Photos**  
**Location Name: Kern- 612N62W / 33NESE**  
**Location #: 318918**



**Photo #5**  
**Kern 43-33** Adandoned battery site  
**Entrance**



**Photo #6**  
**Kern 43-33** Adandoned battery site  
**Weeds**

## Inspection Photos

Location Name: Kern- 612N62W / 33NESE

Location #: 318918



**Photo #7**

**Kern 43-33** Adandoned battery site

**Noxious weeds - Thistle**



**Photo #8**

**Kern 43-33** Adandoned battery site

**Noxious weeds - Thistle**

