

## Inspection Photos

Location Name: Eldridge 4-23 Location ID 323547, Remediation #10672

Inspection Date: 09/24/2018



Photo 1 – Downgradient (southwest) edge of former Tank Battery and Wellpad footprint. Viewing groundwater amendments trench, looking east-southeast.



Photo 2 – Downgradient (south) edge of former Tank Battery and Wellhead footprint. Viewing groundwater amendments trench, looking west.



## Inspection Photos

Location Name: Eldridge 4-23 Location ID 323547, Remediation #10672

Inspection Date: 09/24/2018



**Photo 3 – From south edge of former tank battery and wellpad, looking southwest toward MW-18.**



**Photo 4 – View of outfall of groundwater drain installed on residential development property located adjacent and north (upgradient) of former tank battery.**

