

Inspection Photos

Location Name: Lower Latham PC G 02-22D Tank Battery

Facility ID: 42419



Photo 1 – Stormwater within lined tank berm from recent storms.



Photo 2 – Separator sheds secured.

Inspection Photos

Location Name: Lower Latham PC G 02-22D Tank Battery

Facility ID: 42419



Photo 3 – Heavy channeling and rilling across facility.



Photo 4 – Stormwater transported sediment and trash at south and west perimeters.