

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/20/2018

Submitted Date:

09/25/2018

Document Number:

690300338**FIELD INSPECTION FORM**Loc ID 315308 Inspector Name: Spencer, Stan On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10539Name of Operator: UTAH GAS OP LTD DBA UTAH GAS CORPAddress: 1125 ESCALANTE DRCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:1 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|-----------------|-------|---------------------------|---------|
| Hale, Steve | | shale@utahgascorp.com | |
| Jensen, Charlie | | cjensen@telesto-inc.com | |
| Fischer, Alex | | alex.fischer@state.co.us | |
| Arauza, Steven | | steven.arauza@state.co.us | |

General Comment:

Environmental**Spills/Releases:**

Type of Spill: CONDENSATE

Estimated Spill Volume: -5

Comment: Historic spill from former Wexpro blowdown pit. Pit is ~ 15'X15'x4 ft deep. Pre-closure samples showed max 4300ppm TPH. Pit is dry, netted, and fenced with no surficial stains or odor. One steel discharge pipe drains to center of pit from separator area.

Corrective Action: Soils will be excavated and landfarmed onsite under approved F-27 until Table 910-1 compliance in pit and landfarm. Meet on site with Steve Hale, UGC and Charlie Jensen. Fencing and net will be removed and landfarm area bermed and compacted. 811 utility locates were scheduled but have not been completed so no excavation until 9/24. Provide interim F-27 status reports @ 3months w tilling, fertilizer, and landfarm sampling data until 910-1 compliance.

Date: 08/30/2019

Reportable: _____

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____ Owner Name: _____ GPS : _____

Field Parameters:

Sample Location: _____ Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--------------------|---|
| 690300339 | Pit 104322 9-20-18 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4587804 |