

# *Inspection Photos*

*Loc#413908*

*Operator: Sandridge*

*Inspection Number: 692400138*

*Inspection Date: 9/14/2018*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



**Photo#1:**  
Overview of Location from entry to West.

September14, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Hebron 3-12H Loc#413908



Photo#2:  
Remediation project #9820 in process at Location

September14, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Hebron 3-12H Loc#413908



**Photo#3:**

Unused equipment is stored at Southwest edge of pad perimeter & adjacent to Producing Well.

September14, 2018



**Photo#4:**



Photo#5:

Non Noxious weeds are senescing & dead in Southern Reclamation areas of site.



Photo#6:

September14, 2018



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Inspection Photos: Sandridge Hebron 3-12H Loc#413908