

Inspection Photos

Loc#421227

Operator: Sandridge

Inspection Number: 692400139

Inspection Date: 9/14/2018





Photo#1:
Overview of Location from entry to West.

September14, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Sandridge Coalmont Loc#421227



Photo#2:
Remediation project #9817 in process at Location.

September14, 2018



Photo#5:
Non Noxious weeds are senescing & dead in Reclamation areas of site.



Photo#6:

September14, 2018