

Inspection Photos

API#057-06462

Operator: Sandridge

Inspection Number: 692400144

Inspection Date: 9/13/2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location to Northwest. Site has been heavily grazed this year

September13, 2018



Photo#2:

Mature Canada thistle plants were not visible though rosettes were noted.

September13, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Farleigh Oil PA Silver Spur API#057-06462



Photo#3:


Area not revegetated that had been identified as land farming site has been fenced off.

September13, 2018



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Farleigh Oil PA Silver Spur API#057-06462



Photo#4: Photo#5:
Close up views of ground conditions and vegetation in exclusion area.

September13, 2018