

Inspection Photos
Location Name: Bashor PC / AA17-23
Location #: 306260



Photo #1

Bashor PC AA17-23 (API # 05-123-24320) wellhead

SI - Casing Leak

**Observed audible venting from bottom of well
casing head (Dry vapor - No fluid)**



Photo #2

Bashor PC AA17-23 Battery

