

Location Name: Norris #44-31    API: 071-08074    Inspection Date: 9/25/2018



Location Name: Norris #44-31    API: 071-08074    Inspection Date: 9/25/2018



Location Name: Norris #44-31    API: 071-08074    Inspection Date: 9/25/2018



Location Name: Norris #44-31    API: 071-08074    Inspection Date: 9/25/2018



Berm appears to be inadequate to contain tank volume and freeboard as required per rule.

Location Name: Norris #44-31    API: 071-08074    Inspection Date: 9/25/2018



Berm area calculation.