

Inspection Photos

09/18/2018

Operator: GRAND MESA OPERATING CO #
35080

Location ID: 456610

Inspection Doc. Number: 682503915
Lincoln County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: GRAND MESA OPERATING CO # 35080
Location ID: 456610



Photo 1: Photo of sign on south end of the location.



Photo 2: Photo taken from the south end of the location. Photo shows two porta-johns that have been staked/secured.

Inspection Photos
Operator: GRAND MESA OPERATING CO # 35080
Location ID: 456610



Photo 3: Photo taken from the southwest corner of the location, facing north. Photo shows bales have been installed as a stormwater/erosion control BMP. BMPs appears to have been installed in accordance with good engineering practices. Photo also shows surface roughening along perimeter appears to have been updated/maintained.



Photo 4: Photo taken from the northwest corner of the pad, facing east. Photo shows operator has implemented berms along the perimeter of the pad, and another on the perimeter of the location. Surface roughening has been used in conjunction.

Inspection Photos
Operator: GRAND MESA OPERATING CO # 35080
Location ID: 456610



Photo 5: Photo taken from the northwest corner of the location, facing east. Photo shows operator has implemented berms along the perimeter of the pad, and another on the perimeter of the location. Surface roughening has been used in conjunction.



Photo 6: Photo taken from the northeast corner of the location, facing north. Photo shows additional maintenances appears to have been conducted on surface roughening.