

Inspection Photos
Location Name: Duncan B 13
API: 05-081-07076



Photo 1. Overview of location taken at entrance facing northeast.



Photo 2. Tank labeled with two different contents and no capacity.