

Inspection Photos
Location Name: Duncan "B" 2
API: 05-081-05528



Photo 1. Overview of location taken at entrance facing northwest.



Photo 2. Tank labeled with two different contents and no capacity.