

Inspection Photos
Location Name: WPF III - 66N64W / 18NENW
Location #: 323560



Photo #1

WPF III A18-3 (API # 05-123-13196) P&A wellsite
Within 1/10 mile



Photo #2

WPF III A18-3 Meter run
Unused Equip

Inspection Photos

Location Name: WPF III - 66N64W / 18NENW

Location #: 323560



Photo #3

WPF III A18-3 Meter run

Unused Equip

From previous FIR

