

Inspection Photos
Location Name: DWIGHT G. HANKS B #1
Location ID: 317655



PHOTO 1: WELLHEAD



PHOTO 2: TANK BATTERY

Inspection Photos
Location Name: DWIGHT G. HANKS B #1
Location ID: 317655



PHOTO 3: STAINED SOIL NEAR WEST CRUDE OIL TANK

