

Inspection Photos
Location Name: WPF III - 66N64W /18NWNE
Location #: 323559



Photo #1
WPF III A18-2 (API # 05-123-13195) wellsite



Photo #2
WPF III A18-2 wellhead
Appears SI – valves shut

Inspection Photos

Location Name: WPF III - 66N64W /18NWNE

Location #: 323559



Photo #3

WPF III A18-7, 18-2, Carlson A18-17 Battery

