

Inspection Photos
Location Name: Carlson / A18-17
Location #: 420580



Photo #1

Carlson A18-17 (API # 05-123-32627) wellsite

Weeds




Photo #2

Carlson A18-17 wellhead

Appears SI – valves shut



Inspection Photos
Location Name: Carlson / A18-17
Location #: 420580



Photo #3
WPF III A18-7, 18-2, Carlson A18-17 Battery

