

Inspection Photos
Well Name: South Shale Ridge 3-20
Location ID: 312610



Photo 1: Well has been plugged and cut off.



Photo 2: Parraffin spill appears to have been cleaned up.