

# Inspection Photos

09/24/2018

Operator: DECLAR OIL & GAS INC - #23320

Location ID: 404096

Inspection Doc. Number: 682503929

Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo taken from the north end of the location, facing west. Photo shows tank equipment has been removed and reclamation activities appear to have been conducted.



**Photo 2:** Photo taken from the north end of the location, facing southwest. Photo shows tank equipment has been removed and reclamation activities appear to have been conducted.





**Photo 3:** Photo taken from the north end of the location, facing south. Photo shows tank equipment has been removed and reclamation activities appear to have been conducted.



**Photo 4:** Photo taken from the area of the pits, facing southeast. Photo shows pits appear to have been closed.





**Photo 5:** Photo taken from the area of the pits, facing southeast. Photo shows pits appear to have been closed.



**Photo 6:** Photo taken from the area of the pits, facing east. Photo shows pits appear to have been closed.





**Photo 7:** Photo taken from the access road north of the location, facing north. Photo shows operator appears to have de-compacted, re-contoured and regraded this section of access road.





**Photo 8:** Photo taken from the access road north of the location, facing northwest. Photo shows area of access road that travels to the west that has not been reclaimed per corrective actions.



**Photo 9:** Photo taken from the access road, facing south. Photo shows section of access road that was not reclaimed per corrective actions. Photo also shows culverts remaining.





**Photo 10:** Photo taken from the access road, west of the drainage. Photo shows section of access road that was not reclaimed per corrective actions.



Inspection Photos  
Operator: DECLAR OIL & GAS INC - #23320  
Location ID: 404096



**Photo 11:** Photo from the 1/3/2018 inspection. Photo taken from the western portion of access road. Photo shows cattle guard has not been removed.



**Photo 12:** . Photo taken from the western portion of access road. Photo shows cattle guard has not been removed.



Inspection Photos  
Operator: DECLAR OIL & GAS INC - #23320  
Location ID: 404096



**Photo 13:** Photo from the 1/3/2018 inspection. Photo shows point where access road ended at the fenceline and cattle guard. There was not gate evident, fence had closed off travel/access.



**Photo 14:** Photo taken from the cattle guard, facing west. When compared to photo 13, photo shows access road that was once reclaimed has been re-disturbed.