

Inspection Photos

09/24/2018

Operator: MURFIN DRILLING COMPANY INC -
61650

Location ID: 403738

Inspection Doc. Number: 682503949
Washington County, CO

Aaron Trujillo
NE Reclamation Specialist
COGCC

Inspection Photos
Operator: MURFIN DRILLING COMPANY INC - 61650
Location ID: 403738



Photo 1: Photo from the location, facing north. Photo shows vegetation over the reclamation area.



Photo 2: Photo from the location, facing east. Photo shows vegetation over the reclamation area.

Inspection Photos
Operator: MURFIN DRILLING COMPANY INC - 61650
Location ID: 403738



Photo 3: Photo from the location, facing south. Photo shows vegetation over the reclamation area.



Photo 4: Photo from the location, facing west. Photo shows vegetation over the reclamation area.