

Inspection Photos
Location Name: GEORGE H GERHARDT #1
Location ID: 336278



PHOTO 1: WELLHEAD

PHOTO 2: TANK BATTERY

Inspection Photos
Location Name: GEORGE H GERHARDT #1
Location ID: 336278



PHOTO 3: STAINED SOIL AROUND WELLHEAD

