

**Inspection Photos**  
**Location Name:** Winter / 39-19  
**Location #:** 326733



Colorado Oil & Gas Conservation Commission  
40.46649, -104.58629, 1427.0m, 191°  
2018/09/27 09:55:37 AM

**Photo #1**

**Linda Rae #1 | Winter 39-19, 20-19, 24-19, 40-19  
wellsite**  
**5 – pad wells now P&A'd**



Colorado Oil & Gas Conservation Commission  
40.46587, -104.58395, 1422.0m, 163°  
2018/09/27 10:01:05 AM

**Photo #2**

**Linda Rae #1 | Winter 39-19, 20-19, 24-19, 40-19  
Abandoned Battery site**