

Inspection Photo
Federal 26-3
API # 045-06213
Inspection # 689301995



Location Photo #1



Location Photo #2, missing wellhead sign.

**Inspection Photo
Federal 26-3
API # 045-06213
Inspection # 689301995**



Location Photo #3, uncontrolled weeds in battery containment.



Location Photo #4, uncontrolled weeds in battery containment.

**Inspection Photo
Federal 26-3
API # 045-06213
Inspection # 689301995**



Location Photo #5, missing information on battery sign



Location Photo #6, unused equipment.

