


Location Name: Leah 23-5 wellsite    Spill #456896    Inspection Date: 9/25/2018



Location Name: Leah 23-5 wellsite

Spill #456896

Inspection Date: 9/25/2018



Location Name: Leah 23-5 wellsite

Spill #456896

Inspection Date: 9/25/2018



Dead vegetation found downgradient of pit in direction of arrow.

Location Name: Leah 23-5 wellsite   Spill #456896   Inspection Date: 9/25/2018



Dead vegetation down gradient from produced water pit.



Location Name: Leah 23-5 wellsite    Spill #456896    Inspection Date: 9/25/2018



Dead vegetation down gradient from produced water pit.



Location Name: Leah 23-5 wellsite

Spill #456896

Inspection Date: 9/25/2018



Dead vegetation down gradient from produced water pit.



Location Name: Leah 23-5 wellsite    Spill #456896    Inspection Date: 9/25/2018



Dead vegetation down gradient from produced water pit.