

Inspection Photos

Location Name: OWP Government Baker 1A API 077-5145

09/27/2018



Well looking South



Pit looking East
Well discharge draining South





**Deadman anchor dragged towards pit.
Looking NNW**



**Snowmelt standing water on pad, looking
east**