

Inspection Photos  
Location Name: OWP Flushwell 1 API 077-10327  
09/27/2018



Well looking South



Pit looking East  
**Well looking NE**



**Deadman anchor dragged towards pit.  
Looking NNW**



**Snowmelt standing water on pad, looking  
east**