

Inspection Photos
Location Name: Tillman Burch #1
API: 05-067-06997



Tillman Burch #1 production equipment. Irrigation pipe noted in previous inspection has been moved.



Stock panel enclosure around well head.

Inspection Photos
Location Name: Tillman Burch #1
API: 05-067-06997



Tillman Burch #1 well head.



Location photo facing north from well head.