

Inspection Photos

Location Name: OWP Geowell 1 1 API 077-10326

09/27/2018



Well looking South



Pit looking East
Well looking West





**Deadman anchor dragged towards pit.
Looking NNW**



**Snowmelt standing water on pad, looking
east**