

Inspection Photos

Operator: QEP

API: 05-033-06093

Date: 9/18/2018



Photo 1. View of the project area from the western edge facing center.



Photo 2. View of the northern project area from the western edge facing northeastward.



Photo 3. View of the western project area from the western edge facing southward.



Photo 4. View of the southern project area from the southwestern corner facing eastward.