

# Inspection Photos

Operator: QEP

API: 05-033-06091

Date: 9/18/2018



**Photo 1. View of the project area from the southwestern corner facing center.**





**Photo 2. View of the western project area from the southwestern corner facing northward.**





**Photo 3. View of the southern project area from the southwestern corner facing eastward.**



**Photo 4. View of pit area south of the project area.**