

Inspection Photos
Location Name: Grand 1
Location ID: 320118



Colorado Oil and Gas Conservation Commission
39.96779, -104.65369, 1568.8m
Sep 28, 2018 11:23:56



Colorado Oil and Gas Conservation Commission
39.9681, -104.65352, 1568.6m
Sep 28, 2018 11:27:41

Photo 1 WH

Photo 2 TNK BTRY

Inspection Photos
Location Name: Grand 1
Location ID: 320118



Photo 3 Loc Pic



Photo 4 Bird netting repaired