

Inspection Photos
Location Name: Beebe Draw G26-23
Spill # 455231




Photo 1 – Location Sign



Photo 2 – Site Photo

Inspection Photos
Location Name: Beebe Draw G26-23
Spill # 455231



Photo 3 – Sediment transported off-site in NE corner



Photo 4 – Erosion occurring in NE corner