

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2018

Submitted Date:

09/28/2018

Document Number:

689500858

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: Oakman, Kari On-Site Inspection
2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 100322
Name of Operator: NOBLE ENERGY INC
Address: 1001 NOBLE ENERGY WAY
City: HOUSTON State: TX Zip: 77070

Findings:

- 5 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Axelson, John		john.axelson@state.co.us	
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections
Graber, Candice (Nikki)		candice.graber@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455231	SPILL OR RELEASE	AC	06/13/2018		-	Beebe Draw RG 26-9, 23	EI

General Comment:

COGCC Environmental Inspection of Spill #455231. Any corrective actions from previous inspections that have not been addressed are still applicable.
Photos attached to document site condition at the time of inspection.

Inspected Facilities

Facility ID: 455231 Type: SPILL OR API Number: - Status: AC Insp. Status: EI

Environmental

Spills/Releases:

Type of Spill: CONDENSATE

Estimated Spill Volume: _____

Comment: COGCC Inspection in response to spill 455231. Spill excavation area has been backfilled.

Corrective Action: The Operator shall submit a Form 19 Supplemental Report that documents the successful remediation of the release. Supporting documentation shall include confirmation soil samples to document removal of impacts from soil in the release area and a site diagram that illustrates the release extent and location of confirmation soil samples. If ground water impacts were discovered, the Operator shall submit a Form 27 Site Investigation and Remediation Workplan for the investigation and remediation of impacts to ground water in accordance with Rule 909.c.

Date: 11/27/2018

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat _____ Long _____

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Erosion occurring on in the northeast corner of the site; sediment has been transported off-site. See photos #

Corrective Action: Install or repair required BMPs per Rule 1002.f.

Date: 10/26/2018

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
No surface reclamation of the area has been performed. Operator shall reclaim distrubed area in accordance with 1000 series rules.	oakmank	09/28/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689500859	Inspection Photos 9/27/2018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4593400