

Inspection Photos  
Location Name: Buffalo Ditch 2-32H  
API: 05-057-06464



Photo 1. Soil staining from historical spills at wellhead.




Photo 2. Bradenhead form as filled out and signed in the field.