

**Inspection Photo**  
**Savage RWF 323-28**  
**API # 045-07915**  
**Inspection # 689302013**



**Location Photo #1**



**Location Photo #2**



**Inspection Photo**  
**Savage RWF 323-28**  
**API # 045-07915**  
**Inspection # 689302013**



**Location Photo #3 unmarked deadman near wellheads.**



**Location Photo #4, uncontrolled weeds on location.**

**Inspection Photo**  
**Savage RWF 323-28**  
**API # 045-07915**  
**Inspection # 689302013**



**Location Photo #5, uncontrolled weeds on location.**

