

**Inspection Photo
Savage RMV 180-29
API # 045-07507
Inspection # 689302017**



Location Photo #1,



Location Photo #2, uncontrolled weeds and debris.

Inspection Photo
Savage RMV 180-29
API # 045-07507
Inspection # 689302017



Location Photo #3, non legible battery sign