

**Cascade Creek 608-41**  
**API# 05-045-07519**  
**Inspection# 689701823**



**No emergency contact number on sign.**

**Cascade Creek 608-41**  
**API# 05-045-07519**  
**Inspection# 689701823**





**Cascade Creek 608-41**  
**API# 05-045-07519**  
**Inspection# 689701823**



**Signs not secured and one in the cellar floor. No cap on well.**



**Well sign not readily visible. No cap on well.**

**Cascade Creek 608-41**  
**API# 05-045-07519**  
**Inspection# 689701823**



**Storage of heat tubes in cellars.**



Cascade Creek 608-41  
API# 05-045-07519  
Inspection# 689701823



Faded label on center container.

Cascade Creek 608-41  
API# 05-045-07519  
Inspection# 689701823



Operator name sticker trying to cover out of service sticker.  
Label covering old label with conflicting information.

Cascade Creek 608-41  
API# 05-045-07519  
Inspection# 689701823



Label covering old label with conflicting information.



Stored heat tube in containment.



Cascade Creek 608-41  
API# 05-045-07519  
Inspection# 689701823



Sign not in use.



**Cascade Creek 608-41**  
**API# 05-045-07519**  
**Inspection# 689701823**



**Damaged labels left on tanks.**

**Cascade Creek 608-41**  
**API# 05-045-07519**  
**Inspection# 689701823**



**No Lock out Tag out tag on out of service 1" lines**



**No plugs in valves.**



Cascade Creek 608-41  
API# 05-045-07519  
Inspection# 689701823



No Lock out Tag out tag on out of service 2" lines

**Cascade Creek 608-41**  
**API# 05-045-07519**  
**Inspection# 689701823**



**Sediment build up and erosion of ditch.**



**Cascade Creek 608-41**  
**API# 05-045-07519**  
**Inspection# 689701823**



**Berm on location.**



**Open cellars with no covers or fencing.**

**Cascade Creek 608-41**  
**API# 05-045-07519**  
**Inspection# 689701823**



**No evidence of BMPs off edge of location.**