

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/26/2018

Submitted Date:

09/30/2018

Document Number:

688302530

FIELD INSPECTION FORM

Loc ID 455024 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 74165
Name of Operator: RENEGADE OIL & GAS COMPANY LLC
Address: 6155 S MAIN STREET #210
City: AURORA State: CO Zip: 80016

Findings:

- 8 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Espinosa, Bill	(303) 829-4982	billespinosa30@yahoo.com	All Inspections
Ingve, Ed	(303) 680-4725	ed@renegadeoilandgas.com	All Inspections
Condill, J.B.	(303) 680-4725	jbcrog@aol.com	All Inspections
Quint, Craig		craig.quint@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
455025	WELL	XX	05/16/2018		005-07364	State of Colorado 3-33	DG

General Comment:

Surface Cementing Inspection/Sound readings for complaint 200446279 that were in compliance with COGCC Rules on the night on 9/25/2018. See attached photo for rig lights the night on 9/19/2018, also in compliance. Photo was taken from the top of the access road on west side of location so the stand light was facing west and not toward the complainant's house.

Inspected Facilities

Facility ID: 455025 Type: WELL API Number: 005-07364 Status: XX Insp. Status: DG

Complaint

Comment: Complaint #200446279. Inspector took sound readings the night of 9/25/2018 prior to cementing. All readings were below COGCC noise action levels. Spoke with complainant on 9/26/2018 about when the rig would be gone and that was estimated from the time taken to drill surface.

Corrective Action: _____

Date: _____

Well Drilling

Rig: Rig Name: Nebco Rig 17 Pusher/Rig Manager: Ed Ingve
 Permit Posted: _____ Access Sign: _____

Well Control Equipment:

Pipe Ram: _____ Blind Ram: _____ Hydril Type: _____
 Pressure Test BOP: _____ Test Pressure PSI: _____ Safety Plan: _____

Drill Fluids Management:

Lined Pit: _____ Unlined Pit: _____ Closed Loop: YES Semi-Closed Loop: _____
 Multi-Well: _____ Disposal Location: _____

Comment: Surface TD 2480', 8 5/8" pipe set at 2453'

Corrective Action: _____

Date: _____

Cement

Cement Contractor

Contractor Name: _____ Contractor Phone: _____

Surface Casing

Cement Volume (sx): 995 Circulate to Surface: YES
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: _____

Corrective Action: _____

Date: _____

Completion

Operation: _____

Date Flowback: _____

Contractor: _____

Comment: _____

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit

Interim Reclamation:

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: RANGELAND

Comment:

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment

Corrective Action

Date _____

1002b. SOIL REMOVAL AND SEGREGATION _____

Comment

Corrective Action

Date _____

1002c. PROTECTION OF SOILS _____

Comment

Corrective Action

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment

Corrective Action

Date _____

1003a. Waste and Debris removed? _____

Comment

Corrective Action

Date _____

Unused or unneeded equipment onsite? _____

Comment

Corrective Action

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment

Corrective Action

Date _____

Guy line anchors marked? _____

Comment

Corrective Action

Date _____

1003b. Area no longer in use? _____ Production areas stabilized ? _____
 1003c. Compacted areas have been cross ripped? _____
 1003d. Drilling pit closed? _____ Subsidence over on drill pit? _____
 Cuttings management: _____
 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? _____
 Production areas have been stabilized? _____ Segregated soils have been replaced? _____

RESTORATION AND REVEGETATION

Cropland

Top soil replaced _____ Recontoured _____ Perennial forage re-established _____

Non-Cropland

Top soil replaced _____ Recontoured _____ 80% Revegetation _____

1003e. INTERIM VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

1003 f. Weeds Noxious weeds? _____

Comment

Corrective Action

Date _____

Overall Interim Reclamation

Final Reclamation/ Abandoned Location:

Date Final Reclamation Started: _____ Date Final Reclamation Completed: _____

Final Land Use: RANGELAND _____

Reminder: _____

Comment:

Well plugged _____ Pit mouse/rat holes, cellars backfilled _____

Debris removed _____ No disturbance /Location never built _____

Access Roads Regraded _____ Contoured _____ Culverts removed _____

Gravel removed _____

Location and associated production facilities reclaimed _____ Locations, facilities, roads, recontoured _____

Compaction alleviation _____ Dust and erosion control _____

Non cropland: Revegetated 80% _____ Cropland: perennial forage _____

Weeds present _____ Subsidence _____

1004.d. FINAL VEGETATION TRANSECT
 TRANSECT RESULTS OF DISTURBED AREA% _____
 TRANSECT RESULTS OF REFERENCE AREA% _____
 TOTAL % OF DESIRABLE VEGETATION COVER _____
 VEGETATIVE COVER _____

Comment:

Corrective Action:

Date _____

Overall Final Reclamation _____ Well Release on Active Location Multi-Well Location

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Ditches	Pass			tertiary containment on east side of location
Compaction	Pass	Compaction	Pass	Covering Materials	Pass	
		Check Dams	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688302549	Renegade State of Colorado 3-33 rig lights	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4593768