

# Inspection Photos

Operator: BP America

API: 05-067-06948

Date: 9/25/2018



**Photo 1. View of the project area from the southern corner facing center.**





**Photo 2. View of the southern project area from the southern corner facing westward.**







**Photo 3. View of the southern project area from the southwestern corner facing eastward.**





**Photo 4. View of erosional channel approximately 15 inches deep and 24 inches wide in the northern project area.**