

Inspection Photos
Location Name: Simmons A #3
API: 05-067-09312



Location signs near gate on access road.



Simmons A #2 well head.

Inspection Photos
Location Name: Simmons A #3
API: 05-067-09312



Production equipment along western edge of location.



Wattles on western edge of location, along tributary of Rock Creek.