

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Fitzhugh #11 remediation site.



Fitzhugh #7 remediation site.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Fitzhugh #7.



Fitzhugh #7 well bore.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Fitzhugh #6 pump jack and well head. Stained soil surrounding well.



Location of land farmed material.

Inspection Photos
Location Name: Fitzhugh #6
API: 05-007-05038



Location of sample ID #913181010.



Location of sample ID #913181030.