

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/01/2018

Submitted Date:

10/01/2018

Document Number:

692600418

FIELD INSPECTION FORM

Loc ID 337758 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10489
Name of Operator: AUGUSTUS ENERGY RESOURCES LLC
Address: 2016 GRAND AVENUE #A
City: BILLINGS State: MT Zip: 59102

Findings:

13 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Jones, Greg	(970) 630-3909	greg.jones@ownresources.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
288487	WELL	PR	04/16/2007	GW	125-10564	FIX 2-12	PR

General Comment:

[Routine Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Two track through pasture		
Corrective Action:		Date:	

Overall Good:

Signs/Marker:			
Type	OTHER		
Comment:	Lease signs by meter sheds		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:			
Corrective Action:		Date:	

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Meter sheds and VGS 3/4 fenced with metal panels		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	Metal panels around unit and wellhead		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Wire fence around entire location		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Prime Mover	# 1		
Comment:	Kohler gas engine		
Corrective Action:		Date:	
Type: Gas Meter Run	# 3		
Comment:	Shared meter run for Fix 2-5, 2-10, 2-12		
Corrective Action:		Date:	

Type: Pump Jack	# 1		
Comment:	Jensen unit		
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Gas scrubber and telemetry equipment		
Corrective Action:			Date:
Type: Vertical Separator	# 3		
Comment:	3-Vertical gas separators 50% buried by meter sheds		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 288487 Type: WELL API Number: 125-10564 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Casing production. Central meter run for \(Fix 2-5, 2-10, 2-12\) 370' W of wellhead](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Compaction	Pass			

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT