

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/01/2018

Submitted Date:

10/01/2018

Document Number:

689701849**FIELD INSPECTION FORM**

Loc ID 335798	Inspector Name: LONGWORTH, MIKE	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 22 Number of Comments 2 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested																																																																																																																																															
<b>Operator Information:</b> OGCC Operator Number: <u>10456</u> Name of Operator: <u>CAERUS PICEANCE LLC</u> Address: <u>1001 17TH STREET #1600</u> City: <u>DENVER</u> State: <u>CO</u> Zip: <u>80202</u>																																																																																																																																																			
<b>Contact Information:</b> <table border="1"> <thead> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> </thead> <tbody> <tr> <td>Kellerby, Shaun</td> <td></td> <td>shaun.kellerby@state.co.us</td> <td></td> </tr> <tr> <td>Pesicka, Conor</td> <td></td> <td>conor.pesicka@state.co.us</td> <td></td> </tr> <tr> <td>, Caerus Piceance</td> <td></td> <td>COGCC.inspections@caerusoilandgas.com</td> <td>Piceance inspections only</td> </tr> </tbody> </table>					Contact Name	Phone	Email	Comment	Kellerby, Shaun		shaun.kellerby@state.co.us		Pesicka, Conor		conor.pesicka@state.co.us		, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only																																																																																																																															
Contact Name	Phone	Email	Comment																																																																																																																																																
Kellerby, Shaun		shaun.kellerby@state.co.us																																																																																																																																																	
Pesicka, Conor		conor.pesicka@state.co.us																																																																																																																																																	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only																																																																																																																																																
<b>Inspected Facilities:</b> <table border="1"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>265451</td><td>WELL</td><td>PR</td><td>07/31/2009</td><td>GW</td><td>045-09020</td><td>CHEVRON 22-7D</td><td>PR</td></tr> <tr><td>265452</td><td>WELL</td><td>PR</td><td>08/31/2009</td><td>GW</td><td>045-09019</td><td>CHEVRON 23-7D</td><td>PR</td></tr> <tr><td>265453</td><td>WELL</td><td>SI</td><td>01/01/2017</td><td>GW</td><td>045-09016</td><td>CHEVRON 12-7D</td><td>SI</td></tr> <tr><td>265454</td><td>WELL</td><td>SI</td><td>01/01/2017</td><td>GW</td><td>045-09018</td><td>CHEVRON 13-7D</td><td>SI</td></tr> <tr><td>265455</td><td>WELL</td><td>PR</td><td>03/31/2010</td><td>GW</td><td>045-09017</td><td>CHEVRON 14-7D</td><td>PR</td></tr> <tr><td>265456</td><td>WELL</td><td>PR</td><td>03/31/2010</td><td>GW</td><td>045-09021</td><td>CHEVRON 24-7D</td><td>PR</td></tr> <tr><td>291053</td><td>WELL</td><td>PR</td><td>08/01/2010</td><td>GW</td><td>045-14269</td><td>CHEVRON-MARATHON 12C-7D</td><td>PR</td></tr> <tr><td>291054</td><td>WELL</td><td>PR</td><td>09/01/2010</td><td>GW</td><td>045-14270</td><td>Chevron 12D-7D</td><td>PR</td></tr> <tr><td>291055</td><td>WELL</td><td>PR</td><td>08/01/2009</td><td>GW</td><td>045-14271</td><td>CHEVRON 13A-7D</td><td>PR</td></tr> <tr><td>291056</td><td>WELL</td><td>PR</td><td>03/31/2011</td><td>GW</td><td>045-14272</td><td>Chevron 13C-7D</td><td>PR</td></tr> <tr><td>291057</td><td>WELL</td><td>PR</td><td>09/01/2010</td><td>GW</td><td>045-14273</td><td>Chevron 13D-7D</td><td>PR</td></tr> <tr><td>291058</td><td>WELL</td><td>PR</td><td>09/01/2010</td><td>GW</td><td>045-14274</td><td>Chevron 14A-7D</td><td>PR</td></tr> <tr><td>291059</td><td>WELL</td><td>PR</td><td>10/01/2011</td><td>GW</td><td>045-14275</td><td>CHEVRON 23D-7D</td><td>PR</td></tr> <tr><td>291060</td><td>WELL</td><td>PR</td><td>10/01/2011</td><td>GW</td><td>045-14276</td><td>Chevron 12A-7D</td><td>PR</td></tr> <tr><td>291061</td><td>WELL</td><td>PR</td><td>10/01/2011</td><td>GW</td><td>045-14277</td><td>Chevron 11D-7D</td><td>PR</td></tr> <tr><td>291075</td><td>WELL</td><td>PR</td><td>09/01/2010</td><td>GW</td><td>045-14291</td><td>Chevron 24B-7D</td><td>PR</td></tr> <tr><td>291076</td><td>WELL</td><td>PR</td><td>03/31/2011</td><td>GW</td><td>045-14292</td><td>Chevron 24A-7D</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	265451	WELL	PR	07/31/2009	GW	045-09020	CHEVRON 22-7D	PR	265452	WELL	PR	08/31/2009	GW	045-09019	CHEVRON 23-7D	PR	265453	WELL	SI	01/01/2017	GW	045-09016	CHEVRON 12-7D	SI	265454	WELL	SI	01/01/2017	GW	045-09018	CHEVRON 13-7D	SI	265455	WELL	PR	03/31/2010	GW	045-09017	CHEVRON 14-7D	PR	265456	WELL	PR	03/31/2010	GW	045-09021	CHEVRON 24-7D	PR	291053	WELL	PR	08/01/2010	GW	045-14269	CHEVRON-MARATHON 12C-7D	PR	291054	WELL	PR	09/01/2010	GW	045-14270	Chevron 12D-7D	PR	291055	WELL	PR	08/01/2009	GW	045-14271	CHEVRON 13A-7D	PR	291056	WELL	PR	03/31/2011	GW	045-14272	Chevron 13C-7D	PR	291057	WELL	PR	09/01/2010	GW	045-14273	Chevron 13D-7D	PR	291058	WELL	PR	09/01/2010	GW	045-14274	Chevron 14A-7D	PR	291059	WELL	PR	10/01/2011	GW	045-14275	CHEVRON 23D-7D	PR	291060	WELL	PR	10/01/2011	GW	045-14276	Chevron 12A-7D	PR	291061	WELL	PR	10/01/2011	GW	045-14277	Chevron 11D-7D	PR	291075	WELL	PR	09/01/2010	GW	045-14291	Chevron 24B-7D	PR	291076	WELL	PR	03/31/2011	GW	045-14292	Chevron 24A-7D	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																																																												
265451	WELL	PR	07/31/2009	GW	045-09020	CHEVRON 22-7D	PR																																																																																																																																												
265452	WELL	PR	08/31/2009	GW	045-09019	CHEVRON 23-7D	PR																																																																																																																																												
265453	WELL	SI	01/01/2017	GW	045-09016	CHEVRON 12-7D	SI																																																																																																																																												
265454	WELL	SI	01/01/2017	GW	045-09018	CHEVRON 13-7D	SI																																																																																																																																												
265455	WELL	PR	03/31/2010	GW	045-09017	CHEVRON 14-7D	PR																																																																																																																																												
265456	WELL	PR	03/31/2010	GW	045-09021	CHEVRON 24-7D	PR																																																																																																																																												
291053	WELL	PR	08/01/2010	GW	045-14269	CHEVRON-MARATHON 12C-7D	PR																																																																																																																																												
291054	WELL	PR	09/01/2010	GW	045-14270	Chevron 12D-7D	PR																																																																																																																																												
291055	WELL	PR	08/01/2009	GW	045-14271	CHEVRON 13A-7D	PR																																																																																																																																												
291056	WELL	PR	03/31/2011	GW	045-14272	Chevron 13C-7D	PR																																																																																																																																												
291057	WELL	PR	09/01/2010	GW	045-14273	Chevron 13D-7D	PR																																																																																																																																												
291058	WELL	PR	09/01/2010	GW	045-14274	Chevron 14A-7D	PR																																																																																																																																												
291059	WELL	PR	10/01/2011	GW	045-14275	CHEVRON 23D-7D	PR																																																																																																																																												
291060	WELL	PR	10/01/2011	GW	045-14276	Chevron 12A-7D	PR																																																																																																																																												
291061	WELL	PR	10/01/2011	GW	045-14277	Chevron 11D-7D	PR																																																																																																																																												
291075	WELL	PR	09/01/2010	GW	045-14291	Chevron 24B-7D	PR																																																																																																																																												
291076	WELL	PR	03/31/2011	GW	045-14292	Chevron 24A-7D	PR																																																																																																																																												

Contact Name	Phone	Email	Comment
Kellerby, Shaun		shaun.kellerby@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
, Caerus Piceance		COGCC.inspections@caerusoilandgas.com	Piceance inspections only

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265451	WELL	PR	07/31/2009	GW	045-09020	CHEVRON 22-7D	PR
265452	WELL	PR	08/31/2009	GW	045-09019	CHEVRON 23-7D	PR
265453	WELL	SI	01/01/2017	GW	045-09016	CHEVRON 12-7D	SI
265454	WELL	SI	01/01/2017	GW	045-09018	CHEVRON 13-7D	SI
265455	WELL	PR	03/31/2010	GW	045-09017	CHEVRON 14-7D	PR
265456	WELL	PR	03/31/2010	GW	045-09021	CHEVRON 24-7D	PR
291053	WELL	PR	08/01/2010	GW	045-14269	CHEVRON-MARATHON 12C-7D	PR
291054	WELL	PR	09/01/2010	GW	045-14270	Chevron 12D-7D	PR
291055	WELL	PR	08/01/2009	GW	045-14271	CHEVRON 13A-7D	PR
291056	WELL	PR	03/31/2011	GW	045-14272	Chevron 13C-7D	PR
291057	WELL	PR	09/01/2010	GW	045-14273	Chevron 13D-7D	PR
291058	WELL	PR	09/01/2010	GW	045-14274	Chevron 14A-7D	PR
291059	WELL	PR	10/01/2011	GW	045-14275	CHEVRON 23D-7D	PR
291060	WELL	PR	10/01/2011	GW	045-14276	Chevron 12A-7D	PR
291061	WELL	PR	10/01/2011	GW	045-14277	Chevron 11D-7D	PR
291075	WELL	PR	09/01/2010	GW	045-14291	Chevron 24B-7D	PR
291076	WELL	PR	03/31/2011	GW	045-14292	Chevron 24A-7D	PR

<b>General Comment:</b> Routine General Field Inspection
---

**Location**

<b>Lease Road:</b>			
Type	Main		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Volume on produced water tank showing 00 BBL.		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	11/30/2018
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 866-580-9382

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:			
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:			
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 17	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 17	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:	Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 265451	Type: WELL	API Number: 045-09020	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 265452	Type: WELL	API Number: 045-09019	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 265453	Type: WELL	API Number: 045-09016	Status: SI	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: Shut in since Dec 2016				
Corrective Action:		Date:		
Facility ID: 265454	Type: WELL	API Number: 045-09018	Status: SI	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: Shut in since Dec 2016				
Corrective Action:		Date:		
Facility ID: 265455	Type: WELL	API Number: 045-09017	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 265456	Type: WELL	API Number: 045-09021	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 291053	Type: WELL	API Number: 045-14269	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:		Date:		
Facility ID: 291054	Type: WELL	API Number: 045-14270	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: Producing well				
Corrective Action:		Date:		

<b><u>Producing Well</u></b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291055    Type: WELL    API Number: 045-14271    Status: PR    Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291056    Type: WELL    API Number: 045-14272    Status: PR    Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291057    Type: WELL    API Number: 045-14273    Status: PR    Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291058    Type: WELL    API Number: 045-14274    Status: PR    Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291059    Type: WELL    API Number: 045-14275    Status: PR    Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291060    Type: WELL    API Number: 045-14276    Status: PR    Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291061    Type: WELL    API Number: 045-14277    Status: PR    Insp. Status: PR				
<b><u>Producing Well</u></b>				
Comment:	Producing well			
Corrective Action:			Date:	
Facility ID: 291075    Type: WELL    API Number: 045-14291    Status: PR    Insp. Status: PR				

<b>Producing Well</b>			
Comment:	Producing well		
Corrective Action:		Date:	
Facility ID:	291076	Type:	WELL
API Number:	045-14292	Status:	PR
Insp. Status:	PR		
<b>Producing Well</b>			
Comment:	Producing well		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: [Sediment and shell sloughing on to location behind tank battery.](#)

Corrective Action: [Install or repair required BMPs per Rule 1002.f.](#)

Date: 10/31/2018

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689701851	Inspection 689701849 photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4594798">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4594798</a>