	Location Name	Quarter-Quarter (Example = NESW)	Section (Number Only)	Township (Example = 3N)	Range (Example = 63W)	County (3 Digit County Code)	Latitude	Longitude	P.D.O.P. Reading (#)	Active (Yes or No)	Integrity Testing Method (Example =Pressure Test)	Integrity Test Date	Test Result (Pass/Fail)	Name of Tester
326837	UPRR RICKETSON	NWNW	1	1N	65W	123	40.084018°	-104.621000°	3.3	Yes	Pressure Test	5/18/2017	Pass	Rob Brockett
326837	UPRR RICKETSON	NWNW	1	1N	65W	123	40.084033°	-104.620934°	3.3	Yes	Pressure Test	5/18/2017	Pass	Rob Brockett
326837	UPRR RICKETSON	NWNW	1	1N	65W	123	40.083793°	-104.620889°	3.3	Yes	Pressure Test	3/20/2017	Pass	Jasen Mrozak
326837	UPRR RICKETSON	NWNW	1	1N	65W	123	40.083818°	-104.620888°	3.3	Yes	Hydraulic Head	5/23/2017	Pass	Nate Sears
326837	UPRR RICKETSON	NWNW	1	1N	65W	123	40.083985°	-104.621035°	3.3	Yes	Pressure Test	5/27/2017	Pass	Rob Brockett
326837	UPRR RICKETSON	NWNW	1	1N	65W	123	40.084033°	-104.620934°	3.3	Yes	Pressure Test	5/27/2017	Pass	Rob Brockett
326837	UPRR RICKETSON	NWNW	1	1N	65W	123	40.083793°	-104.620889°	3.3	Yes	Pressure Test	5/27/2017	Pass	Rob Brockett
326837	UPRR RICKETSON	NWNW	1	1N	65W	123	40.083793°	-104.620889°	3.3	Yes	Pressure Test	5/18/2017	Pass	Rob Brockett