

Inspection Photos

Operator: BP America

API: 05-067-08881

Date: 9/25/2018



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is progressing with grasses such as western wheatgrass (*Pascopyrum smithii*) and intermediate wheatgrass (*Thinopyron intermedium*).





Photo 3. View of the northern project area from the northeastern corner facing westward.



Photo 4. View of the western project area from the northwestern corner facing southward.