

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/02/2018

Submitted Date:

10/02/2018

Document Number:

678301866**FIELD INSPECTION FORM**Loc ID 434539 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
434538	WELL	PR	05/20/2014	GW	123-38236	Peppler K26-79-1HN	EI
434540	WELL	PR	08/20/2014	GW	123-38237	Peaks K26-78-1HN	EI
434541	WELL	PR	05/21/2014	GW	123-38238	Peaks K26-77-1HN	EI

General Comment:[battery located to south and inspected separately](#)

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	CH3OH containers labeled		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Equipment:			corrective date
Type: Plunger Lift	# 3		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
METHANOL	2	OTHER	PBV STEEL		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	100 gallons
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Other	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:	secondary containment (BMPs) unser each tank		
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	<u>434538</u>	Type:	<u>WELL</u>	API Number:	<u>123-38236</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>434540</u>	Type:	<u>WELL</u>	API Number:	<u>123-38237</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>
Facility ID:	<u>434541</u>	Type:	<u>WELL</u>	API Number:	<u>123-38238</u>	Status:	<u>PR</u>	Insp. Status:	<u>EI</u>